

**REVISED**EPA FORM 2070-12 (7-81)



<input checked="" type="checkbox"/> A TOXIC	<input checked="" type="checkbox"/> E SOLUBLE	<input checked="" type="checkbox"/> I HIGHLY VOLATILE
<input checked="" type="checkbox"/> B CORROSIVE	<input type="checkbox"/> F INFECTIOUS	<input type="checkbox"/> J EXPLOSIVE
<input type="checkbox"/> C RADIOACTIVE	<input checked="" type="checkbox"/> G FLAMMABLE	<input type="checkbox"/> K REACTIVE
<input checked="" type="checkbox"/> D PERSISTENT	<input checked="" type="checkbox"/> H IGNITABLE	<input type="checkbox"/> L INCOMPATIBLE
		<input type="checkbox"/> M NOT APPLICABLE

CATEGORY	SUBSTANCE NAME	01 GROSS AMOUNT	02 UNIT OF MEASURE	03 COMMENTS
SLU	SLUDGE			Waste oil "soup" contained many types of chemicals. This was used to oil the internal roads @ facility. This mixture also had 1-2% 1,1,1 Trichloroethane in it also.
OLW	OILY WASTE	unk		
SOL	SOLVENTS	unk		
PSD	PESTICIDES			
OCC	OTHER ORGANIC CHEMICALS	unk		
IOC	INORGANIC CHEMICALS			
ACD	ACIDS	unk		
BAS	BASES	unk		
MES	HEAVY METALS			

[illegible]

CATEGORY	01 FEEDSTOCK NAME	02 CAS NUMBER	CATEGORY	01 FEEDSTOCK NAME	02 CAS NUMBER
FDS			FDS		
FDS			FDS		
FDS			FDS		
FDS			FDS		



POTENTIAL HAZARDOUS WASTE SITE  
PRELIMINARY ASSESSMENT  
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER  
IND 980607576

II. HAZARDOUS CONDITIONS AND INCIDENTS

01 ☒ A GROUNDWATER CONTAMINATION 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☒ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED 10,000+ 04 NARRATIVE DESCRIPTION  
7 wells on property- used by employees. Migration of Trichloroethane into groundwater may have occurred.

01 ☒ B SURFACE WATER CONTAMINATION 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☒ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED 10,000+ 04 NARRATIVE DESCRIPTION  
On property, lake used for fishing and boating. Runoff from roads may have carried Trichloroethane and PCB's into lake.

01 ☐ C CONTAMINATION OF AIR 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☐ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED \_\_\_\_\_ 04 NARRATIVE DESCRIPTION

Unknown

01 ☐ D FIRE EXPLOSIVE CONDITIONS 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☐ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED \_\_\_\_\_ 04 NARRATIVE DESCRIPTION

Unknown

01 ☒ E DIRECT CONTACT 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☒ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED 10,000+ 04 NARRATIVE DESCRIPTION  
Waste oil spread on roads to control dust. It is probable that individuals were bare-footed on these roads. PCB's are a contact hazard.

01 ☒ F CONTAMINATION OF SOIL 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☒ POTENTIAL ☐ ALLEGED  
03 AREA POTENTIALLY AFFECTED 320 04 NARRATIVE DESCRIPTION  
(Acres)  
Waste oil used for dust control. Possible addition of PCB's to waste oil..PCB's adhere to soil particles and are very persistent.

01 ☒ G DRINKING WATER CONTAMINATION 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☒ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED 10,000+ 04 NARRATIVE DESCRIPTION  
7 wells on property used by employees. Property open year round and used by employees and their families.

01 ☐ H WORKER EXPOSURE INJURY 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☐ POTENTIAL ☐ ALLEGED  
03 WORKERS POTENTIALLY AFFECTED \_\_\_\_\_ 04 NARRATIVE DESCRIPTION

Unknown

01 ☐ I POPULATION EXPOSURE INJURY 02 ☐ OBSERVED (DATE \_\_\_\_\_) ☐ POTENTIAL ☐ ALLEGED  
03 POPULATION POTENTIALLY AFFECTED \_\_\_\_\_ 04 NARRATIVE DESCRIPTION

Unknown



POTENTIAL HAZARDOUS WASTE SITE  
PRELIMINARY ASSESSMENT  
PART 3 - DESCRIPTION OF HAZARDOUS CONDITIONS AND INCIDENTS

I. IDENTIFICATION

01 STATE 02 SITE NUMBER  
IND 980607576

II. HAZARDOUS CONDITIONS AND INCIDENTS (Continued)

01 ☒ J. DAMAGE TO FLORA  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL ☐ ALLEGED

Vegetation along roads may have been damaged.

01 ☒ K. DAMAGE TO FAUNA  
04 NARRATIVE DESCRIPTION (Include name(s) of species)

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL ☐ ALLEGED

Local fauna may have been damaged.

01 ☒ L. CONTAMINATION OF FOOD CHAIN  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL ☐ ALLEGED

PCB's and Trichloroethane bioaccumulate, especially in fish.

01 ☒ M. UNSTABLE CONTAINMENT OF WASTES  
(Spills, runoff, standing liquids, leaking drums)

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL ☐ ALLEGED

03 POPULATION POTENTIALLY AFFECTED: 10,000+ 04 NARRATIVE DESCRIPTION

Spraying of contaminated oil on roads constitutes unstable containment of wastes.

01 ☒ N. DAMAGE TO OFFSITE PROPERTY  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☒ POTENTIAL ☐ ALLEGED

Possible migration of chemicals to neighboring properties.

01 ☐ O. CONTAMINATION OF SEWERS, STORM DRAINS, WWTPs  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL ☐ ALLEGED

Unknown

01 ☐ P. ILLEGAL/UNAUTHORIZED DUMPING  
04 NARRATIVE DESCRIPTION

02 ☐ OBSERVED (DATE: \_\_\_\_\_)

☐ POTENTIAL ☐ ALLEGED

Unknown

05 DESCRIPTION OF ANY OTHER KNOWN, POTENTIAL, OR ALLEGED HAZARDS

III. TOTAL POPULATION POTENTIALLY AFFECTED: 10,000+

IV. COMMENTS

Need PCB soil samples beside roads and in lake area.  
Roads have all been asphalted.

V. SOURCES OF INFORMATION (Give specific references e.g. state files, sample analysis reports)

Wes. Charpie- Cummins Engine Co.  
ISHH files - Industry, CERCLA



## FIELD PHOTOGRAPHY LOG SHEET

Page 1DATE 4/16/85TIME 11:05 (A.M.) P.M.DIRECTION: N NNE NE ENE  
E ESE SE SSE  
(S) SSW SW WSW  
W WNW NW NNWWEATHER 70°FSunnySITE CerelandTDD# ROS-8410-02A

PHOTOGRAPHED BY:

Arlene Pratt

SAMPLE ID# (if applicable)

N/ADESCRIPTION: ENTRANCE off 525 EAST ROAD into  
CerelandDATE 4/16/85TIME 11:05 (A.M.) P.M.DIRECTION: N NNE NE ENE  
E ESE SE SSE  
S SSW SW WSW  
(W) WNW NW NNWWEATHER 70°FSunnySITE CerelandTDD# ROS-8410-02A

PHOTOGRAPHED BY:

Arlene Pratt

SAMPLE ID# (if applicable)

N/ADESCRIPTION: Sign showing location of facilities.  
FIRST FORK in ROAD after entrance into PARK



## FIELD PHOTOGRAPHY LOG SHEET

Page 2DATE 4/16/85TIME 11:10 A.M. P.M.DIRECTION: N NNE NE ENE  
E ESE SE SSE  
S SSW SW WSW  
W WNW NW NNWWEATHER 70°FSunnySITE CerelandTDD# ROS-8410-02APHOTOGRAPHED BY: Arlene Pratt

SAMPLE ID# (if applicable)

N/ADESCRIPTION: Cereland Lake - Person fishing in lake.

DATE \_\_\_\_\_

TIME \_\_\_\_\_ A.M. P.M.

DIRECTION: N NNE NE ENE  
E ESE SE SSE  
S SSW SW WSW  
W WNW NW NNW

WEATHER \_\_\_\_\_

SITE \_\_\_\_\_

TDD# \_\_\_\_\_

PHOTOGRAPHED BY: \_\_\_\_\_

SAMPLE ID# (if applicable)

DESCRIPTION: \_\_\_\_\_

PHOTO